

Alazar delivered the strongest overall performance (89.5/100). The installation was well planned, accurate and professionally executed. The rubric confirms full marks in safety, commissioning, wiring, protection, equipment installation and functionality. Motor forward/reverse control, interlocking, overload protection, lighting and socket circuits all operated correctly. The photos also show a well-organized and carefully constructed installation.

Only minor improvement was needed in P3 leveling. The main lost marks came from the challenge task, which was not completed; the internal panel wiring could also be dressed slightly more neatly.

Score 89.5%

Check othe